

**ABC Townhome Association
 Inspection Check List
 Inspection Date: Srping, Current Year**

Unit	Roof	Siding/Paint	Windows	Trees	Shrubs	Lawn	Driveway	Sidewalks & Patios	Other
123	Shingle raised on north side					Overseed side yard.	Cracked		
124				Green Ash needs treatment					
125			Loose weather stripping on side window.				Cracked		Lint in dryer vent.
126					Remove dead shrub in front				
127						Overseed side yard			
128								Crack on garage apron.	Front light fixture broken
129		Paint around garage door peeling.			Replace spirea in front bed.	Dead spots from dog.	Cracked		
130								Sidewalk slab by porch slants toward building	
131						Overseed back			